



501/6
 □ 6
 H=75
 L=30



502/6
 □ 6
 H=75
 L=45



503/6
 □ 6
 H=100
 L=40



504/6
 □ 6
 H=130
 L=65



506/6
 □ 6
 H=240
 L=55



507/6
 □ 6
 H=190
 L=100



508/6
 □ 6
 H=165
 L=60



509/6
 □ 6
 H=145
 L=50



505/6
 □ 6
 Ø70



521/10
 □ 10
 H=110
 L=65



522/10
 □ 10
 H=130
 L=60



523/10
 □ 10
 H=135
 L=65



524/10
 □ 10
 H=190
 L=100



525/10
 □ 10
 H=245
 L=55



526/12
 □ 12
 H=170
 L=95



527/12
 □ 12
 H=190
 L=90

